

6070068

1




FIG. 1




FIG. 2




FIG. 3

FIG. 5A




FIG. 5B



FIG. 4A





FIG. 4B






FIG. 6A CALL INCOMING




FIG. 6B CLICK




FIG. 6C




FIG. 6D CLICK




FIG. 6E




FIG. 6F




FIG. 6G




FIG. 7

FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 9E




FIG. 9F




FIG. 10A

1 0311111111 Act 0:01:30	
2 0622222222 Hold 0:02:44	

↓ TURN ON CALL CONTROL KEY

FIG. 10B

1 0311	2 062222
Disc	Act
Hold	Act
MP	MP

↓ DOWN

FIG. 10C


1 0311	2 062222
Disc	Act
Hold	Act
MP	MP

↓ CLICK

FIG. 10D


1 0311111111 Hold 0:01:33	
2 0622222222 Act 0:00:01	

FIG. 11A




↓ TURN ON CALL CONTROL KEY

FIG. 11B




↓ DOWN

FIG. 11C




↓ CLICK

FIG. 11D



↓ DOWN

FIG. 11E



↓ CLICK

FIG. 11F

